

**Virginia Department of Environmental Quality**  
**Appendix 4 - Fact Sheets for**  
**Impaired (Category 4 or 5) Waters in 2022**

---

**James River Basin**

**Cause Group Code:** **H26R-04-BEN** **South Fork Rivanna River**

Cause Location: South Fork Rivanna River from the RWSA SF Rivanna River Public Water Intake downstream to its confluence with the Rivanna River. (Start Mile: 3.47 End Mile: 0.00 Total Impaired Size: 3.47 Miles)

Cause City/County: Albemarle County

Use(s): Aquatic Life

Causes(s)/VA Category: Benthic Macroinvertebrates Bioassessments/5A

Cause Description: This segment is impaired due to exceedances of the General Standard for Benthics at stations: 2-RRS001.81 (Impaired for VSCI) and 2-RRS-RVN31-RCA (Impaired for VSCI). Initial Listing Date: 2010.

Assessment Unit / Water Name / Location Desc.	Cause Category	Cause Name	Cycle First Listed	TMDL Dev. Priority	Water Size
VAV-H26R_RRS01A00 / Rivanna River South Fork / South Fork Rivanna River from the RWSA SF Rivanna River Public Water Intake downstream to its confluence with the Rivanna River.	5A	Benthic Macroinvertebrates Bioassessments	2010	H	3.47

South Fork Rivanna River

**Aquatic Life**

Benthic Macroinvertebrates Bioassessments - Total Impaired Size by Water Type:

Estuary (Sq. Miles)	Reservoir (Acres)	River (Miles)
		3.47

Sources: Dam or Impoundment; Municipal (Urbanized High Density Area); Non-Point Source